Approved For Release 2002/07/22 : CIA-RDP61-00763A000200090102-1

DPD-6714-59

6 October 1959

MEMORANDUM PER: Acting Chief, DPD-DD/P

SUBJECT

: Malfunction Report, Period Ending 30 September 1959

1. The following malfunction information is presented for the period ending 30 September 1959:

I. Communications

A. Detachment "B"

- System III. Two failures of the third local oscillator board discriminator. One failure was on Mission 8638.
- System VI. One instance of jamed tape and one instance of loss of the 3KC marker tone were reported.
- 3. SYstem VII. During Mission 4137 a blower motor in a power supply failed which caused several components to overheat and burn out.

B. Detackment "C"

Failure of the System III and VI on Missions 6037, 6036, 6042, and 6044. Only partial success was reported on Mission 6040. Total equipment malfunctions were 6 each recorders, 6 each third local oscillator boards, 2 each info amplifier power supplies, 1 each distributed amplifier and 1 each timer. The reason for the malfunctions was based on turning the equipment on at altitude, a procedure which has been standard at Detachment "B" for this equipment.

II. Photographic Equipment

A. During the period 1 September 1959 through 30 September there were a total of twenty-two missions reported flown using photographic againment. Equipments malfunctioned on two of these missions giving an everall effectiveness of 91%.

Approved For Release 2002/07/22: CIA-RDP61-00763A000200090102-1

DPD-6714-59 PAGE TWO

II. Photographic Equipment (Cont'd)

B. Equipment reliability for the above referenced period was:

	A-1 Com.	A-2 Conf.	B Conf.	Trackers
Missions Flown	o	3	12	21
Malfunctions	Ø	0	0	2
Per Cent Eff.	0	100%	100%	90.05%

C. On Mission No. CT-59-56 the tracker, SR-9, was demaged and was returned to the depot for repairs and overheul.

Chief, Material Branch

25X1A

25X1A

MB/DPD-DD/P
Dist: O = A/CE/DPD
1 - DD/P
1 - C/GPS/DPD
1 - C/MAT/DPD
2 - RI/DPD